



Greyhound Lines, Inc.

# Drivers Bulletin ~ DB-132

Coaches Involved:  
**G4500 (7282~7301)**


Topic:  
**New Amaya Driver's Seat Adjustment Controls**

Date:  
**8/20/2004**

**Lumbar Support Adjustment**




**Cushion Height Adjustment**



**Forward~Rearward Adjustment**



**Backrest Recline**



**Height~Weight Support Adjustment**



## WARNING



DO NOT attempt adjustment of the driver's seat while coach is in motion. The seat could suddenly and unexpectedly move causing the driver to lose control of the vehicle. Make all seat adjustments before starting the engine and while the coach is not moving.